

# NTSB Identification: SEA74AS018

14 CFR Part 91 General Aviation  
 Aircraft: CESSNA 402B, registration: N69307

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-2864	73/9/29 TIME - 1910	UTICA, MONT	CESSNA 402B N69307 DAMAGE-DESTROYED	CR- PX- OT-	1 7 0	0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	COMMERCIAL, FL.INSTR., AGE 22, 1112 TOTAL HOURS, 81 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION						
STANFORD, MONT		LOCAL						
TYPE OF ACCIDENT				PHASE OF OPERATION				
STALL				IN FLIGHT: BUZZING				
PROBABLE CAUSE(S)								
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING								
FACTOR(S)								
PILOT IN COMMAND - PHYSICAL IMPAIRMENT								
MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT								
FIRE AFTER IMPACT								
REMARKS- BUZZED TAVERN TWICE, LDG LTS ON, THEN LOST CTL. PLT BLOOD ALCOHOL LEVEL 0.09 GMS PCT.								

Full narrative is not available