

NTSB Identification: LAX76AL068

14 CFR Part 135 Nonscheduled operation of AIR CATALINA
 Aircraft: GRUMMAN G-21A, registration: N18CS

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0751	76/4/10 TIME - 1620	NR.AVALON,CA	GRUMMAN G-21A N18CS DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 9 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG	ATP,FLIGHT INSTR., AGE 38, 11517 TOTAL HOURS, 1376 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
CAMP FOX,CATALINA,CA		SAN PEDRO,CA				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: CLIMB TO CRUISE		
COLLISION WITH GROUND/WATER: CONTROLLED				LANDING: LEVEL OFF/TOUCHDOWN		
PROBABLE CAUSE(S)						
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS						
PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING						
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES,DIRECTIVES,ETC.						
PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS						
FACTOR(S)						
MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES						
MISCELLANEOUS ACTS,CONDITIONS - INCORRECT TRIM SETTING						
MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER						
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER						
REMARKS- L ENG LOST PWR.DIDNT FEATH PROP.UN MAINTAIN ALT, LND CROSS SWELL.L FLOAT SEP.ACFT SANK IN OCEAN.						

Full narrative is not available