

NTSB Identification: ANC75AA085

14 CFR Part 135 Nonscheduled operation of WOODS AIR SERV
Aircraft: DEHAVILLAND DHC-3, registration: N90574

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-1366	75/5/21	ANCHORAGE,AK	DEHAVILLAND DHC-3	CR-	1	0 0	COMMERCIAL	COMMERCIAL, FL.INSTR., AGE 35, 2768 TOTAL HOURS, 20 IN TYPE, NOT INSTRUMENT RATED.
	TIME - 0905		N90574	PX-	0	0 0	AIR TAXI-CARGO	
			DAMAGE-SUBSTANTIAL	OT-	0	0 0		
NAME OF AIRPORT - LAKE HOOD STRIP								
DEPARTURE POINT		INTENDED DESTINATION			LAST ENROUTE STOP			
LAKE HOOD,AK		ANIAK,AK			ANCHORAGE,AK			
TYPE OF ACCIDENT				PHASE OF OPERATION				
STALL: MUSH				TAKEOFF: INITIAL CLIMB				
PROBABLE CAUSE(S)								
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
FACTOR(S)								
PILOT IN COMMAND - LACK OF FAMILIARITY WITH AIRCRAFT								
MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.								
MISCELLANEOUS ACTS,CONDITIONS - INCORRECT TRIM SETTING								
FIRE AFTER IMPACT								
REMARKS- DMGD 5 CARS,LUMBER STACK & FENCE. ACFT AT LEAST 484 LBS OVR MAX GROSS WT,CG UNK.								

Full narrative is not available