

NTSB Identification: MIA77FKQ09

14 CFR Part 135 Nonscheduled operation of MILLER AIR TRA
Aircraft: CESSNA 402, registration: N4530Q

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0770	77/3/17	MADISON,MS	CESSNA 402	CR-	0	0	1	COMMERCIAL
	TIME - 1945		N4530Q	PX-	0	0	0	AIR TAXI-CARGO
			DAMAGE-DESTROYED	OT-	0	0	0	COMMERCIAL, AGE 30, 2700 TOTAL HOURS, 125 IN TYPE, INSTRUMENT RATED.
	NAME OF AIRPORT - BRUCE CAMPBELL							
	DEPARTURE POINT		INTENDED DESTINATION					
	MEMPHIS,TN		JACKSON,MS					
	TYPE OF ACCIDENT		PHASE OF OPERATION					
	ENGINE FAILURE OR MALFUNCTION		IN FLIGHT: DESCENDING					
	COLLIDED WITH: TREES		LANDING: FINAL APPROACH					
	PROBABLE CAUSE(S)							
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING							
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING							
	PILOT IN COMMAND - MISMANAGEMENT OF FUEL							
	MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION							
	FACTOR(S)							
	TERRAIN - HIGH OBSTRUCTIONS							
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES							
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND							

Full narrative is not available