

NTSB Identification: FTW77FRG27

14 CFR Part 91 General Aviation
Aircraft: BEECH D18S, registration: N762D

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0470	77/2/19	MC ALLEN,TX	BEECH D18S	CR-	1	0 0	NONCOMMERCIAL	AIRLINE TRANSPORT, AGE
	TIME - 1047		N762D	PX-	0	0 0	PLEASURE/PERSONAL TRANSP	42, 13258 TOTAL HOURS,
			DAMAGE-DESTROYED	OT-	0	0 0		2002 IN TYPE, INSTRUMENT
								RATED.
		NAME OF AIRPORT - MILLER INTERNATNL						
		DEPARTURE POINT		INTENDED DESTINATION				
		MC ALLEN,TX		LAREDO,TX				
		TYPE OF ACCIDENT			PHASE OF OPERATION			
		ENGINE FAILURE OR MALFUNCTION			TAKEOFF: INITIAL CLIMB			
		STALL: MUSH			IN FLIGHT: UNCONTROLLED DESCENT			
		PROBABLE CAUSE(S)						
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
		MISCELLANEOUS ACTS,CONDITIONS - WATER IN FUEL						
		PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
		FIRE AFTER IMPACT						
		REMARKS- ACFT LAST REFUELED ON 10/21/76 AND PARKED OUTSIDE. NO WITNESSES OBSERVED PREFLIGHT INSPECTION.						

Full narrative is not available