## NTSB Identification: FTW78FA028

14 CFR Part 91 General Aviation Aircraft: PIPER PA-31, registration: N6751L

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N				FLIGHT PURPOSE	PILOT DATA
3-0155	78/2/18 TIME - 170	SEARCY,AR 15	PIPER PA-31 N6751L DAMAGE-DESTROYED		0	1	1	INSTRUCTIONAL CHECK	COMMERCIAL, FL.INSTR., AGE 38, 6025 TOTAL HOURS, 2579 IN TYPE, INSTRUMENT RATED.

DEPARTURE POINT INTENDED DESTINATION LOCAL

SEARCY, AR TYPE OF ACCIDENT PHASE OF OPERATION
LANDING: ROLL
LANDING: GO-AROUND GROUND-WATER LOOP-SWERVE COLLIDED WITH: TREES

PROBABLE CAUSE(S)
PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT
DUAL STUDENT - FAILED TO MAINTAIN DIRECTIONAL CONTROL
PILOT IN COMMAND - EXERCISED POOR JUDGMENT
REMARKS- ATTEMPTED SINGLE ENG GO-AROUND DURING TNG, PLT TRAINEE 0-TIME IN TYPE.

Full narrative is not available