

NTSB Identification: FTW78DRG59

14 CFR Part 91 General Aviation
Aircraft: BEECH G18S, registration: N807P

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2111	78/7/5 TIME - 0500	MC ALLEN, TX	BEECH G18S N807P DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 1 OT- 0 0 0	NONCOMMERCIAL BUSINESS	COMMERCIAL, AGE 56, 16660 TOTAL HOURS, 2060 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - MILLER INTL						
DEPARTURE POINT		INTENDED DESTINATION				
MC ALLEN, TX		TAMPICO, MEX				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB		
COLLIDED WITH: DITCHES				TAKEOFF: ABORTED		
PROBABLE CAUSE(S)						
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS						
FACTOR(S)						
AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: OTHER						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
REMARKS- AIRCRAFT STRUCK DRAINAGE DITCH.						

Full narrative is not available