

NTSB Identification: FTW79FA015

14 CFR Part 135 Nonscheduled operation of LARRY JOHNSON  
Aircraft: BEECH H18, registration: N204CC

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3937	78/11/20 TIME - 2000	BROWNSVILLE, TX	BEECH H18 N204CC DAMAGE-DESTROYED	CR- PX- OT-	1 0 0	0 0 0	COMMERCIAL AIR TAXI-CARGO	COMMERCIAL, FL.INSTR., AGE 27, 3550 TOTAL HOURS, 258 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - BROWNSVILLE INTL								
DEPARTURE POINT		INTENDED DESTINATION						
BROWNSVILLE, TX		SPRINGFIELD,MO						
TYPE OF ACCIDENT				PHASE OF OPERATION				
COLLISION WITH GROUND/WATER: UNCONTROLLED				IN FLIGHT: UNCONTROLLED DESCENT				
PROBABLE CAUSE(S)								
MISCELLANEOUS - UNDETERMINED								
FACTOR(S)								
WEATHER - LOW CEILING								
WEATHER - FOG								
WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE								
WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT								
SKY CONDITION				CEILING AT ACCIDENT SITE				
OVERCAST				300				
VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE				
1 MILE OR LESS				NONE				
OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F				
FOG				61				
WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS				
330				7				
TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN				
IFR				IFR				
FIRE AFTER IMPACT								
REMARKS- WRECKAGE LOCATION 3MI FROM DEPARTURE ARPT.								

Full narrative is not available