

NTSB Identification: MKC79FA046

14 CFR Part 91 General Aviation
 Aircraft: MITSUBISHI MU-2B, registration: N208MA

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2769	79/8/3 TIME - 2125	HAYS,KS	MITSUBISHI MU-2B N208MA DAMAGE-DESTROYED	CR- 1 0 0 PX- 6 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	COMMERCIAL, AGE 34, 2168 TOTAL HOURS, 140 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - HAYS MUNICIPAL						
DEPARTURE POINT		INTENDED DESTINATION				
SALINA,KS		DENVER,CO				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE		
STALL: MUSH				LANDING: GO-AROUND		
PROBABLE CAUSE(S)						
POWERPLANT - COMPRESSOR ASSEMBLY: BEARING, ROTOR SHAFT						
MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE						
PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING						
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - PRECAUTIONARY LANDING ON AIRPORT						
FIRE AFTER IMPACT						
REMARKS- FORWARD MAIN SHAFT BEARING, SN P61208, FAILED.						

Full narrative is not available