

NTSB Identification: OAK79DAMS7

14 CFR Part 91 General Aviation
 Aircraft: DOUGLAS DC-3, registration: N63250

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4002	79/7/20 TIME - 1930	NR.HONOLULU,HI	DOUGLAS DC-3 N63250 DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	MISCELLANEOUS FERRY	AIRLINE TRANSPORT, AGE 35, 8000 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT SAN JOSE,CA		INTENDED DESTINATION HONOLULU,HI		PHASE OF OPERATION		
TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION DITCHING				IN FLIGHT: NORMAL CRUISE LANDING: LEVEL OFF/TOUCHDOWN		
PROBABLE CAUSE(S) PILOT IN COMMAND - BECAME LOST/DISORIENTED MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
FACTOR(S) INSTRUMENTS/EQUIPMENT AND ACCESSORIES - COMMUNICATIONS AND NAVIGATION EQUIPMENT: OTHER INSTRUMENTS/EQUIPMENT AND ACCESSORIES - COMMUNICATIONS AND NAVIGATION EQUIPMENT: LORAN RECEIVER MISCELLANEOUS ACTS,CONDITIONS - COMMUNICATIONS FAILURE MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER						
REMARKS- ACFT NOT RECOVERED,INJURIES/DAMAGE PRESUMED.PLT RPRT HF RADIO & LORAN INOP,LOST,NO FUEL,DITCHING.						

Full narrative is not available