## NTSB Identification: DEN80FA012

14 CFR Part 91 General Aviation Aircraft: MITSUBISHI MU-2B, registration: N200BR

FILE	DATE LOCATIO	N AIRCRAFT DATA		F	S M	/N	FLIGHT PURPOSE	PILOT DATA
3-3693	79/12/21 PROVO,UT TIME - 1758	MITSUBISHI MU-2B	CR- PX-	1	0 0	0 0	NONCOMMERCIAL CORP/EXEC	AIRLINE TRANSPORT, AGE
	NAME OF AIRPORT - PROVO MUNI							
	DEPARTURE POINT							
	DENVER, CO.	PROVO,UT.						
	TYPE OF ACCIDENT				PHASE OF OPERATION			
	COLLISION WITH GROUND/WATER: CONTROLLED LANDING: TRAFFIC PATTERN-CIRCLING PROBABLE CAUSE(S)							
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING							
	PILOT IN COMMAND - IMPROPER IFR OPERATION PLOT IN COMMAND - IMPROPER IFR OPERATION							
	PILOT IN COMMAND -							
	FACTOR(S)							
	WEATHER - RAIN							
	MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER							
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE							
		ECAST SUBSTANTIALLY CORRECT	-					
	SKY CONDITION			C			AT ACCIDENT SITE	
	OVERCAST			_	_	500		
	VISIBILITY AT ACCIDENT			Р			TATION AT ACCIDENT S	TIE
	5 OR OVER(UNLIMITED)			_	RA		TURE-F	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE			'	3		TORE-F	
					_		LOCITY-KNOTS	
	UNKNOWN/NOT REPORTED			٨				
	WIND DIRECTION-DEGREES			h		V	LOCITI-KNOTS	
					6		FLIGHT PLAN	
	WIND DIRECTION-DEGREES 330				6	OF		

Full narrative is not available