

NTSB Identification: NYC80FA010

14 CFR Part 91 General Aviation
 Aircraft: AEROSTAR 601P, registration: N8099J

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3966	79/11/16 TIME - 1215	CHARLSTADT,NJ	AEROSTAR 601P N8099J DAMAGE-DESTROYED	CR- 1 0 0 PX- 2 0 0 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC	AIRLINE TRANSPORT, AGE 37, 8300 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - TETERBORO DEPARTURE POINT TETERBORO,NJ INTENDED DESTINATION UNIVERSITY PARK,PA TYPE OF ACCIDENT FIRE OR EXPLOSION: IN FLIGHT PHASE OF OPERATION IN FLIGHT: CLIMB TO CRUISE PROBABLE CAUSE(S) PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT POWERPLANT - EXHAUST SYSTEM: STACKS MISCELLANEOUS ACTS,CONDITIONS - FATIGUE FRACTURE MISCELLANEOUS ACTS,CONDITIONS - FIRE IN ENGINE FACTOR(S) MISCELLANEOUS ACTS,CONDITIONS - SEPARATION IN FLIGHT FIRE AFTER IMPACT REMARKS- EXHAUST PIPE ASSEMBLY PART NR 32006-511 FAILED AT FLANGE WELD.						

Full narrative is not available