NTSB Identification: LAX81FA042

14 CFR Part 135 Nonscheduled operation of WESTERN STATES Aircraft: BEECH H18, registration: N787Q

FILE		AIRCRAFT DATA	F S M/N		PILOT DATA
3-3146		BEECH H18	CR- 1 0 0 PX- 1 0 0	AIR TAXI-CARGO	ATP,FLIGHT INSTR., AGE 32, 4054 TOTAL HOURS, 200 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT INTENDED DESTINATION LAST ENROUTE STOP VAN NUYS,CA SALT LAKE CITY,UT LAS VEGAS,NV TYPE OF ACCIDENT PHASE OF OPERATION ENGINE FAILURE OR MALFUNCTION IN FLIGHT: NORMAL CRUISE COLLISION WITH GROUND/WATER: CONTROLLED IN FLIGHT: DESCENDING				
	PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF POWERPLANT & POWERPLANT CONTROLS MISCELLANEOUS ACTS, CONDITIONS - ANTI-ICING/DEICING EQUIPMENT-IMPROPER OPERATION OF/OR FAILED TO USE MISCELLANEOUS ACTS, CONDITIONS - ICE-CARBURETOR FACTOR(S) WEATHER - RAIN WEATHER - CONDITIONS CONDUCIVE TO CARB./INDUCTION SYSTEM ICING PILOT IN COMMAND - PHYSICAL IMPAIRMENT				
	MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 2 ENGINES WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND SKY CONDITION CEILING AT ACCIDENT SITE				
	OVERCAST VISIBILITY AT ACCIDENT UNKNOWN/NOT REPORTED OBSTRUCTIONS TO VISION UNKNOWN/NOT REPORTED TYPE OF WEATHER CONDITI	AT ACCIDENT SITE	UNKN PRECIP RAIN TEMPER 52	OWN/NOT REPORTED ITATION AT ACCIDENT SI	TE.

Full narrative is not available