NTSB Identification: CHI82FEX01

14 CFR Part 91 General Aviation Aircraft: PIPER PA-31T, registration: N15SS

FILE	DATE	LOCATION	AIRCRAFT DATA			RIES S M		FLIGHT PURPOSE	PILOT DATA
3-3217	81/11/30 TIME - 171	MADISON,IN L5	PIPER PA-31T N15SS DAMAGE-SUBSTANTIAL	PX-	0	4	0	NONCOMMERCIAL CORP/EXEC	AIRLINE TRANSPORT, AGE 33, 7126 TOTAL HOURS, 1305 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - MADISON MUNI
DEPARTURE POINT INTENDED DESTINATION

LOUISVILLE, KY

PHASE OF OPERATION

PERUJIN LOU
TYPE OF ACCIDENT
ENGINE FAILURE OR MALFUNCTION IN FLIGHT: NORMAL CRUISE GEAR COLLAPSED LANDING: LEVEL OFF/TOUCHDOWN

PROBABLE CAUSE(S)

PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING PILOT IN COMMAND - MISMANAGEMENT OF FUEL

MISCELLANEOUS ACTS, CONDITIONS - FUEL EXHAUSTION

FACTOR(S)

POWERPLANT - POWERPLANT-INSTRUMENTS: FUEL QUANTITY GAUGE

MISCELLANEOUS ACTS, CONDITIONS - ERRATIC

TERRAIN - ROUGH/UNEVEN

COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES

EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND

Full narrative is not available