

NTSB Identification: ANC81FA089

14 CFR Part 135 Nonscheduled operation of AURORA AIR SER
 Aircraft: BEECH C-45H, registration: N9826Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3600	81/8/1 TIME - 1425	NR.LIVENGOOD,AK	BEECH C-45H N9826Z DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-CARGO	AIRLINE TRANSPORT, AGE 48, 11028 TOTAL HOURS, 530 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
BARROW,AK		FAIRBANKS,AK				
TYPE OF ACCIDENT				PHASE OF OPERATION		
COLLIDED WITH: TREES				IN FLIGHT: OTHER		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS						
FACTOR(S)						
WEATHER - LOW CEILING						
WEATHER - RAIN						
WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE						
WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT						
SKY CONDITION				CEILING AT ACCIDENT SITE		
UNKNOWN/NOT REPORTED				UNKNOWN/NOT REPORTED		
VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE		
UNKNOWN/NOT REPORTED				RAIN		
OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TYPE OF WEATHER CONDITIONS		
UNKNOWN/NOT REPORTED				IFR		
TYPE OF FLIGHT PLAN						
VFR						
FIRE AFTER IMPACT						
REMARKS- CRASHED IN WOODED MOUNTAINOUS AREA NR PIPELINE.ANOTHER PLT CIRCUMNAVIGATED LOW CIGS IN CRASH AREA.						

Full narrative is not available