



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Instrument flying instruction

OR COMMANDING OFFICER'S REPORT:

Court of Inquiry.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: 19-8-41

COMPOSITION:

Pilot was carrying unauthorized low flying whilst attempting to turn hit tree on upper slope.

PRESIDENT - S/L CARRER, A MM  
MEMBER - F/L INGRAM, G.L.  
MEMBER - F/O JACOBS, D.S.

RECOMMENDATIONS:

SUPPLYING OF ALL TRIN ENGINED SCHOOLS WITH ONE OR MORE SINGLE ENGINE AIRCRAFT OF A SUITABLE TYPE TO ENABLE INSTRUCTORS TO "LET OFF STEAM". NOT CONCURRED IN BY A.F.H.Q.

PRIMARY CAUSE:

Unauthorized low flying

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

*JACO/POL*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Wiped off starboard side tail plane aircraft then crashed in timber on mountain.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_