## NTSB Identification: NYC67A0007

14 CFR Part 121 Scheduled operation of PIEDMONT AVIATION INC Aircraft: MARTIN M-404, registration: N40446

FILE	DATE	LOCATION	AIRCRAFT DATA			IES S M/	FLIGHT N PURPOSE	PILOT DATA
1-0042	66/7/9 TIME - 095	ROANOKE VA 54	MARTIN M-404 N40446 DAMAGE-SUBSTANTIAL	PX-	0	1 3		ATP,FLIGHT INSTR., AGE 42, 17500 TOTAL HOURS, 1853 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - WOODRUM
OPERATOR - PIEDMONT AVIATION, INC.
TYPE OF ACCIDENT
GEAR COLLARSED

GEAR COLLAPSED

PROBABLE CAUSE(S)

PERSONNEL - MAINTENANCE, SERVICING, INSPECTION: IMPROPER MAINTENANCE (MAINTENANCE PERSONNEL)

SYSTEMS - HYDRAULIC SYSTEM: RESERVOIR, LINES, FITTINGS

AIRFRAME - LANDING GEAR: SWITCHES, LEVERS, CRANKING MECHANISM, ETC.

MISCELLANEOUS ACTS, CONDITIONS - DISREGARD OF GOOD OPERATING PRACTICE

REMARKS- LDG GR PINS NOT IN.ON HYD TEST, GR HANDLE MOVED UP DUE EXC CLNC IN SEL VALVE AND AIR IN HYD SYSTEM.

Full narrative is not available

PHASE OF OPERATION

STATIC: PARKED-ENGINES NOT OPERATING