

NTSB Identification: DIA68A0031

14 CFR Part 91 General Aviation
Aircraft: PIPER PA-31, registration: N9098Y

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0280	68/1/20 TIME - 1217	TOBACCOVILLE,NC	PIPER PA-31 N9098Y DAMAGE-DESTROYED	CR- 2 0 0 PX- 4 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	COMMERCIAL, AGE 46, 9000 TOTAL HOURS, 31 IN TYPE, INSTRUMENT RATED.
TYPE OF ACCIDENT		STALL: SPIN		PHASE OF OPERATION		
PROBABLE CAUSE(S)		PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED		IN FLIGHT: OTHER		
FIRE AFTER IMPACT		REMARKS- PLT IS BELIEVED TO HAVE BEEN PRACTISING STALLS. ENTERED FLAT SPIN.				

Full narrative is not available