

NTSB Identification: MKC69A0039

14 CFR Part 91 General Aviation
Aircraft: MITSUBISHI MU-2B, registration: N3550X

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4630	68/12/21 TIME - 1010	NR.SPRINGFIELD,MO	MITSUBISHI MU-2B N3550X DAMAGE-DESTROYED	CR- 1 0 0 PX- 4 0 0 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, FL.INSTR., AGE 35, 2910 TOTAL HOURS, 100 IN TYPE, INSTRUMENT RATED.
TYPE OF ACCIDENT			PHASE OF OPERATION			
COLLISION WITH GROUND/WATER: UNCONTROLLED			IN FLIGHT: UNCONTROLLED DESCENT			
PROBABLE CAUSE(S)						
MISCELLANEOUS - UNDETERMINED						
FACTOR(S)						
PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT						
FIRE AFTER IMPACT						
REMARKS- MALFUNCTION OF ARTIFICIAL HORIZON AND TURN NEEDLE. ACFT OBSERVED TO CRASH FROM VERTICAL DIVE.						

Full narrative is not available