## NTSB Identification: NYC69A0018

14 CFR Part 135 Scheduled operation of BUKER AIRWAYS\* Aircraft: BEECH D18S, registration: N7110N

FILE	DATE	LOCATION	AIRCRAFT DATA			IES S M		FLIGHT PURPOSE	PILOT DATA
3-3135	68/8/10 TIME - 002	JAMAICA,NY 3	BEECH D18S N7110N DAMAGE-DESTROYED	PX-	0	0	0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	ATP,FLIGHT INSTR., AGE 42, 11200 TOTAL HOURS, 1015 IN TYPE, INSTRUMENT

NAME OF AIRPORT - J.F.K. TYPE OF ACCIDENT TURBULENCE

COLLISION WITH GROUND/WATER: UNCONTROLLED PROBABLE CAUSE(S)
MISCELLANEOUS - VORTEX TURBULENCE

PILOT IN COMMAND - MISJUDGED DISTANCE FACTOR(S)

MISCELLANEOUS ACTS,CONDITIONS - FAILED TO USE ALL AVAILABLE RUNWAY MISCELLANEOUS ACTS,CONDITIONS - CONGESTED TRAFFIC-PATTERN

REMARKS- PLT ENCOUNTERED TURB FROM JET WHILE MAKING T/O FROM INTERSECTION. LOCAL CNTRL WARNED PLT OF TURB.

Full narrative is not available

PHASE OF OPERATION
TAKEOFF: INITIAL CLIMB

IN FLIGHT: UNCONTROLLED DESCENT