

NTSB Identification: IAD70AI061

14 CFR Part 91 General Aviation  
Aircraft: CESSNA 401, registration: N4077Q

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-1082	70/5/27	SPRUCE PINE,NC	CESSNA 401	CR-	1	0	0	NONCOMMERCIAL	COMMERCIAL, FL.INSTR., AGE 38, 7686 TOTAL HOURS, 1400 IN TYPE, INSTRUMENT RATED.
	TIME - 0930		N4077Q	PX-	0	0	0	CORP/EXEC	
			DAMAGE-DESTROYED	OT-	0	0	0		
DEPARTURE POINT		INTENDED DESTINATION							
ASHEVILLE,NC		UNKNOWN/NOT REPORTED							
TYPE OF ACCIDENT				PHASE OF OPERATION					
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE					
COLLIDED WITH: TREES				LANDING: FINAL APPROACH					
PROBABLE CAUSE(S)									
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS									
PILOT IN COMMAND - MISJUDGED CLEARANCE									
TERRAIN - HIGH OBSTRUCTIONS									
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE									
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND									
FIRE AFTER IMPACT									
REMARKS- CAUSE OF L ENG MALFUNCTION NOT DETERMINED DUE GRND FIRE.HIT TOP 25FT TREE IMPACTED ROAD.EMBANKMENT									

Full narrative is not available