

NTSB Identification: DEN70AD046

14 CFR Part 135 Scheduled operation of ROCKY MOUNTAIN*
 Aircraft: AERO COMDR 680V, registration: N6359U

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0033	70/1/22 TIME - 0806	ASPEN, COLO	AERO COMDR 680V N6359U DAMAGE-DESTROYED	CR- 1 0 0 PX- 7 0 0 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	ATP, FLIGHT INSTR., AGE 35, 5865 TOTAL HOURS, 525 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - SARDY FLD DEPARTURE POINT DENVER, COLO INTENDED DESTINATION ASPEN, COLO TYPE OF ACCIDENT COLLISION WITH GROUND/WATER: CONTROLLED PHASE OF OPERATION LANDING: GO-AROUND PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: FAILURE TO PROVIDE ADEQ. DIRECTIVES, MANUAL, EQUIPMENT TERRAIN - HIGH OBSTRUCTIONS MISCELLANEOUS ACTS, CONDITIONS - ICE-WINDSHIELD FACTOR(S) PILOT IN COMMAND - FAILED TO USE OR INCORRECTLY USED MISC. EQUIPMENT SYSTEMS - ANTI-ICING, DE-ICING SYSTEMS: WINDSHIELD ANTI-ICING, DE-ICING SYSTEMS WEATHER - ICING CONDITIONS-INCLUDES SLEET, FREEZING RAIN, ETC. WEATHER BRIEFING - BRIEFED BY WEATHER BUREAU PERSONEL, BY PHONE WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT SKY CONDITION PARTIAL OBSCURATION CEILING AT ACCIDENT SITE 5000 VISIBILITY AT ACCIDENT SITE 5 OR OVER (UNLIMITED) PRECIPITATION AT ACCIDENT SITE SNOW OBSTRUCTIONS TO VISION AT ACCIDENT SITE NONE TEMPERATURE-F 30 WIND VELOCITY-KNOTS CALM TYPE OF WEATHER CONDITIONS VFR TYPE OF FLIGHT PLAN NONE REMARKS- PLT DIDNT FOLLOW CO INFORMAL GOARND PRO.NO GOARND PRO IN CO OPNS MAN.MT OBSCD BY ICE ON WINDSHIELD						

Full narrative is not available