

NTSB Identification: NYC71FHD13

14 CFR Part 91 General Aviation
 Aircraft: NOORDUYN UC-64, registration: N1207

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-1453	70/8/2 TIME - 1144	LAKEWOOD,NJ	NOORDUYN UC-64 N1207 DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 2 7 OT- 0 0 0	MISCELLANEOUS PARAJUMP-SPORT	COMMERCIAL, AGE 27, 1520 TOTAL HOURS, 30 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - LAKEWOOD						
DEPARTURE POINT		INTENDED DESTINATION				
LAKEWOOD,NJ		LOCAL				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB		
COLLIDED WITH: TREES				LANDING: FINAL APPROACH		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION						
TERRAIN - HIGH OBSTRUCTIONS						
FACTOR(S)						
MISCELLANEOUS ACTS,CONDITIONS - FUEL SELECTOR POSITIONED BETWEEN TANKS						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
REMARKS- L FUEL TANK EMPTY R FUEL TANK APRX 12GALS.FUEL SELECTOR FOUND POS BETWEEN L AND R TANK.						

Full narrative is not available