

NTSB Identification: MKC72AK064

14 CFR Part 135 Nonscheduled operation of SMYER AIRCRAFT
 Aircraft: BEECH E18S, registration: N234AP

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0751	72/6/3 TIME - 0930	WINFIELD, KANS	BEECH E18S N234AP DAMAGE-DESTROYED	CR- 1 PX- 1 OT- 0	0 0 0	0 0 0	COMMERCIAL AIR TAXI-CARGO	COMMERCIAL, FL.INSTR., AGE 44, 14226 TOTAL HOURS, 1200 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION		PHASE OF OPERATION				
ARKANSAS CITY, KANS		WHITE PLAINS, NY		IN FLIGHT: NORMAL CRUISE				
TYPE OF ACCIDENT				IN FLIGHT: UNCONTROLLED DESCENT				
FIRE OR EXPLOSION: IN FLIGHT								
AIRFRAME FAILURE: IN FLIGHT								
PROBABLE CAUSE(S)								
MISCELLANEOUS ACTS, CONDITIONS - FIRE IN ENGINE								
MISCELLANEOUS ACTS, CONDITIONS - FIRE IN WING								
FACTOR(S)								
MISCELLANEOUS ACTS, CONDITIONS - SEPARATION IN FLIGHT								
REMARKS- IN FLT FIRE FROM UNDETERMINED SOURCE CAUSED L WG SEPARATION. L PROP FOUND FEATH.								

Full narrative is not available