

NTSB Identification: LAX72AL054

14 CFR Part 91 General Aviation
 Aircraft: BEECH 3TM, registration: N6674

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0764	72/5/13 TIME - 1650	VAN NUYS,CALIF	BEECH 3TM N6674 DAMAGE-DESTROYED	CR- 1 0 0 PX- 2 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	COMMERCIAL, FL.INSTR., AGE 30, 875 TOTAL HOURS, 37 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - VAN NUYS DEPARTURE POINT INTENDED DESTINATION VAN NUYS,CALIF LOCAL TYPE OF ACCIDENT PHASE OF OPERATION GROUND-WATER LOOP-SWERVE TAKEOFF: RUN COLLIDED WITH: BUILDING(S) TAKEOFF: INITIAL CLIMB PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO MAINTAIN DIRECTIONAL CONTROL PILOT IN COMMAND - FAILED TO ABORT TAKEOFF FACTOR(S) WEATHER - UNFAVORABLE WIND CONDITIONS PILOT IN COMMAND - LACK OF FAMILIARITY WITH AIRCRAFT WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT SKY CONDITION CEILING AT ACCIDENT SITE CLEAR UNLIMITED VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE 5 OR OVER(UNLIMITED) NONE OBSTRUCTIONS TO VISION AT ACCIDENT SITE RELATIVE BEARING OF WIND NONE LEFT QUARTERING HEAD WIND 293-337 DEGREES WIND DIRECTION-DEGREES WIND VELOCITY-KNOTS 280 15 TYPE OF WEATHER CONDITIONS TYPE OF FLIGHT PLAN VFR NONE FIRE AFTER IMPACT REMARKS- PLT REPTD TO HAVE ABOUT 1 HR DUAL IN TYPE.ACFT HIT HANGAR,BE-35 N5312E AND BE-23 N2380L,DESTROYED.						

Full narrative is not available