## NTSB Identification: Unknown

14 CFR Part 91 General Aviation Aircraft: LOCKHEED PV-1, registration: N175S

F S M/N PURPOSE	
TIME - 2045 N175S PX- 1 0 0 UNKNOWN/NOT REPORTED 29, UNK/NR T DAMAGE-DESTROYED OT- 0 0 0 UNK/NR IN TY	T DATA
	YPE, UNK/NR
DEPARTURE POINT INTENDED DESTINATION	
MIAMI,FLA UNKNOWN/NOT REPORTED	
TYPE OF ACCIDENT PHASE OF OPERATION	
HARD LANDING LEVEL OFF/TOUCHDOWN	
PROBABLE CAUSE(S)	
PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING	
PILOT IN COMMAND - IMPROPER LEVEL OFF	
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.	
PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: INADEQUATE SUPERVISION OF FLIGHT CREW	
FIRE AFTER IMPACT	
REMARKS- NO FLT PLAN.FAILED TO REPORT ENTERING COUNTRY.LNDD OFF ARPT.INVESTIGATED & REPORTED BY COLUMBI	IA.

Full narrative is not available