## NTSB Identification: DEN73FQD20

14 CFR Part 91 General Aviation Aircraft: BEECH D18S, registration: N26Q

FILE	DATE LOCATION		AIRCRAFT DATA			RIES S M		FLIGHT PURPOSE	PILOT DATA	
3-1525	73/6/16 TIME - 073	CLOUDCROFT,N MEX 30	BEECH D18S N26Q DAMAGE-DESTROYED	CR- PX- OT-	0	0	0		COMMERCIAL, AGE 32, 2400 TOTAL HOURS, 140 IN TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - TIMBERON									
	DEPARTURE POINT TIMBERON,N MEX		FENDED DESTINATION EL PASO,TEX							
	TYPE OF ACCIDENT			PHASE OF OPERATION						
	COLLIDED WITH: TREES				TAKEOFF: RUN					
	PROBABLE CAUSE(S)									
	PILOT IN COMMAND - DELAYED ACTION IN ABORTING TAKEOFF									
	PILOT IN COMMAND - SELECTED WRONG RUNWAY RELATIVE TO EXISTING WIND									
	FACTOR(S)  MISCELLANEOUS ACTS,CONDITIONS - DOWNWIND  TERRAIN - HIGH OBSTRUCTIONS  FIRE AFTER IMPACT									

Full narrative is not available