

NTSB Identification: NYC74DNA09

14 CFR Part 91 General Aviation
Aircraft: BEECH C18S, registration: N44565

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-1974	73/7/30	NR.W.FALMOUTH,MASS	BEECH C18S	CR-	0	0	1	NONCOMMERCIAL
			N44565	PX-	0	0	0	PLEASURE/PERSONAL TRANSP
			DAMAGE-DESTROYED	OT-	0	0	0	COMMERCIAL, AGE 54, 2700
			DEPARTURE POINT					TOTAL HOURS, 280 IN TYPE,
			NORFOLK,MASS					NOT INSTRUMENT RATED.
			INTENDED DESTINATION					
			LOCAL					
			TYPE OF ACCIDENT					
			ENGINE FAILURE OR MALFUNCTION					
			DITCHING					
			PROBABLE CAUSE(S)					
			PILOT IN COMMAND - MISMANAGEMENT OF FUEL					
			MISCELLANEOUS ACTS,CONDITIONS - INATTENTIVE TO FUEL SUPPLY					
			MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION					
			MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES					
			FACTOR(S)					
			MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER					
			COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES					
			EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER					
			REMARKS- PILOT EXHAUSTED FUEL FROM RIGHT TANK UNABLE TO RESTART ON LEFT TANK AIRCRAFT SANK AFTER DITCHING.					

Full narrative is not available