

NTSB Identification: MIA74AM038

14 CFR Part 129 Scheduled operation of OTHER-FOREIGN FLAG CARRIER
Aircraft: DOUGLAS DC-6B, registration: N614SE

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
A-0005	73/10/25	NR.MIAMI,FLA	DOUGLAS DC-6B	CR-	0	2	1	SCHED INTERNATL CARGO SRV
	TIME - 0038		N614SE	PX-	0	0	0	AIRLINE TRANSPORT, AGE
			DAMAGE-DESTROYED	OT-	0	0	0	52, 22000 TOTAL HOURS,
								6000 IN TYPE, INSTRUMENT
								RATED.
		OPERATOR - OTHER-FOREIGN FLAG CARRIER						
		DEPARTURE POINT		INTENDED DESTINATION				
		GEORGETOWN,GUYANA		MIAMI,FLA				
		TYPE OF ACCIDENT			PHASE OF OPERATION			
		ENGINE FAILURE OR MALFUNCTION			IN FLIGHT: NORMAL CRUISE			
		DITCHING			LANDING: LEVEL OFF/TOUCHDOWN			
		PROBABLE CAUSE(S)						
		POWERPLANT - FUEL SYSTEM: OTHER						
		MISCELLANEOUS ACTS,CONDITIONS - LEAK/LEAKAGE						
		PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
		MISCELLANEOUS ACTS,CONDITIONS - INATTENTIVE TO FUEL SUPPLY						
		PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING						
		MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
		FACTOR(S)						
		MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER						
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-4 ENGINES						
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER						
		REMARKS- GUYANA AIRWAYS.DITCHED IN BISCAYNE BAY.LK NO 3 MN FUEL SYS.OVERFLEW NASSAU & BIMINI WITH LOW FUEL.						

Full narrative is not available