

NTSB Identification: FTW74AF045

14 CFR Part 135 Scheduled operation of TRICON AIRLIN*
 Aircraft: BEECH C-45H, registration: N2122

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3803	73/12/20 TIME - 2026	WACO,TEX	BEECH C-45H N2122 DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-CARGO S-D	COMMERCIAL, AGE 26, 3116 TOTAL HOURS, 930 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - MADISON COOPER						
DEPARTURE POINT		INTENDED DESTINATION		LAST ENROUTE STOP		
DALLAS,TEX		RETURN		WACO,TEX		
TYPE OF ACCIDENT				PHASE OF OPERATION		
STALL				LANDING: TRAFFIC PATTERN-CIRCLING		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.						
EMERGENCY CIRCUMSTANCES - PRECAUTIONARY LANDING ON AIRPORT						
REMARKS- PLT RPRTD AFTR TKOF HE WOULD HAVE TO RET & LND.CG 3.38IN AFT REAR LMT.						

Full narrative is not available