## NTSB Identification: FTW74AF056

14 CFR Part 91 General Aviation Aircraft: DASSAULT FALCON, registration: N7824M

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA
3-0141	74/1/18 TIME - 1845		DASSAULT FALCON N7824M DAMAGE-DESTROYED	PX-	0	0	0	NONCOMMERCIAL CORP/EXEC	AIRLINE TRANSPORT, AGE 43, 7400 TOTAL HOURS, 350 IN TYPE, INSTRUMENT RATED.
	NAME OF AIRPORT - MEACHAM								
	DEPARTURE F	POINT	INTENDED DESTINATION						
	MONTGOMER	RY,ALA	FT.WORTH, TEX						
	TYPE OF ACCIDENT				Р	HAS			
	COLLIDED WITH: DIRT BANK			LANDING: ROLL					
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - SELECTED WRONG RUNWAY RELATIVE TO EXISTING WIND								
	PILOT IN COMMAND - FAILED TO USE OR INCORRECTLY USED MISC.EQUIPMENT								
	MISCELLANEOUS ACTS,CONDITIONS - HYDROPLANING ON WET RUNWAY								
	AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: WET RUNWAY								
	FACTOR(S)								
	WEATHER - RAIN								
	MISCELLANEOUS ACTS,CONDITIONS - DOWNWIND WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY RADIO								
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY RADIO WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT								
	SKY CONDITI		SOBSTANTIALLY CONNECT		C	FTI	ING	AT ACCIDENT SITE	
	OVERCAST				3000				
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE				
	3 MILES OR LESS				RAIN SHOWERS, THUNDERSTORM				
	OBSTRUCTION	CIDENT SITE		RELATIVE BEARING OF WIND					
	NONE				TA	ΕL	WIND 158-202 DEGREES		
	TEMPERATURE-F 50				W	IND 8	VE	LOCITY-KNOTS	
	TYPE OF WEATHER CONDITIONS VFR				TYPE OF FLIGHT PLAN IFR				
	REMARKS- CLRD ILS CIRCLING APCH, PLT REO STRAIGHT IN. LND NORMALLY IN HEAVY RAIN. DIDN'T DEPLOY DRAG								PLOY DRAG CHUTE

Full narrative is not available