

NTSB Identification: CHI74AC046

14 CFR Part 135 Nonscheduled operation of KARNs INTERNAT
 Aircraft: BEECH C-45H, registration: N9909Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-4098	73/12/5 TIME - 0008	PLYMOUTH, MICH	BEECH C-45H N9909Z DAMAGE-DESTROYED	CR- PX- OT-	0 0 0	1 0 0	COMMERCIAL AIR TAXI-CARGO	AIRLINE TRANSPORT, AGE 27, 5013 TOTAL HOURS, 3169 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - METTETAL DEPARTURE POINT INTENDED DESTINATION YPSILANTI, MICH ST LOUIS, MO TYPE OF ACCIDENT PHASE OF OPERATION ENGINE FAILURE OR MALFUNCTION LANDING: FINAL APPROACH HARD LANDING LANDING: LEVEL OFF/TOUCHDOWN PROBABLE CAUSE(S) PILOT IN COMMAND - MISMANAGEMENT OF FUEL PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING MISCELLANEOUS ACTS, CONDITIONS - FUEL EXHAUSTION PILOT IN COMMAND - IMPROPER LEVEL OFF FACTOR(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND REMARKS- VECTORS TO ALT ARPT DUE LO FUEL. BOTH ENG FAILED BEFORE FIELD IN SIGHT.								

Full narrative is not available