NTSB Identification: ANC75AA075

14 CFR Part 135 Scheduled operation of MUNZ NORTHERN* Aircraft: BRITTNORMAN BN-2A, registration: N591JA

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N				PILOT DATA	
3-0476	TIME - 1220			PX-	0	0 1	COMMUTER AIR CARRIER	COMMERCIAL, AGE 32, 1243 R TOTAL HOURS, 284 IN TYPE, INSTRUMENT RATED.	
				ON LAST ENROUTE STOP KK TIN CITY,AK					
	TYPE OF ACCIDENT UNDERSHOOT			PHASE OF OPERATION LANDING: FINAL APPROACH R: CONTROLLED LANDING: FINAL APPROACH					
	PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED DISTANCE AND ALTITUDE PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS PILOT IN COMMAND - DELAYED IN INITIATING GO-AROUND WEATHER - DOWNDRAFT, UPDRAFTS								
	FACTOR(S) WEATHER - SNOW TERRAIN - HIGH OBSTRUCTIONS								
	WEATHER BRIEFING - PARTIAL BRIEFING BY FLIGHT SERVICE PERSONNEL, BY PHONE/RADIO, LIMITED BY PILOT ACTION WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT								
	SKY CONDITION PARTIAL OBSCURATION VISIBILITY AT ACCIDENT SITE 1/4 MILE OR LESS				CEILING AT ACCIDENT SITE UNKNOWN/NOT REPORTED PRECIPITATION AT ACCIDENT SITE RAIN				
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE BLOWING SNOW				TEMPERATURE-F 2				
	WIND DIRECTION-DEGREES 350				WIND VELOCITY-KNOTS 24				
		HER CONDITIONS			T		FLIGHT PLAN		

Full narrative is not available