

NTSB Identification: DEN75DQD28

14 CFR Part 91 General Aviation
 Aircraft: BEECH TC-45G, registration: N9430Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-1415	75/6/12 TIME - UNK/NR	STEINS,NM	BEECH TC-45G N9430Z DAMAGE-SUBSTANTIAL	CR- 0 0 1 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	CERTIFICATE UNKNOWN, AGE UNK/NR, UNK/NR TOTAL HOURS, UNK/NR IN TYPE, UNK/NR INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
UNKNOWN/NOT REPORTED		UNKNOWN/NOT REPORTED				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE		
COLLIDED WITH: DITCHES				LANDING: ROLL		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
FACTOR(S)						
TERRAIN - ROUGH/UNEVEN						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
REMARKS- ILLICIT TRANS OF MARIJUANA. LND ON DRY LAKE BED & HIT DITCH. ACFT ABANDONED. INJ INDEX PRESUMED.						

Full narrative is not available