

NTSB Identification: NYC77FNA07

14 CFR Part 91 General Aviation
 Aircraft: TED SMITH 601, registration: N90337

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4102	76/12/12 TIME - 1800	FRAMINGHAM CTR,MA	TED SMITH 601 N90337 DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 1 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	COMMERCIAL, AGE 52, 5000 TOTAL HOURS, 1600 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT BOSTON,MA	INTENDED DESTINATION WHITE PLAINS,NY			PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE LANDING: LEVEL OFF/TOUCHDOWN	
	TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION COLLIDED WITH: TREES					
	PROBABLE CAUSE(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING PILOT IN COMMAND - MISMANAGEMENT OF FUEL MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES					
	FACTOR(S) POWERPLANT - POWERPLANT-INSTRUMENTS: FUEL QUANTITY GAUGE COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND					

Full narrative is not available