## NTSB Identification: FTW78FA002

14 CFR Part 91 General Aviation Aircraft: LEAR 25B, registration: N100EP

FILE	DATE	LOCATION	AIRCRAFT DATA	 JUR F			FLIGHT PURPOSE	PILOT DATA
3-2202	77/10/5 TIME - 194	AMARILLO,TX 13	LEAR 25B N100EP DAMAGE-DESTROYED	 0	0	1	NONCOMMERCIAL CORP/EXEC	AIRLINE TRANSPORT, AGE 32, 3250 TOTAL HOURS, 920 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - AMARILLO INTL
DEPARTURE POINT INTENDED DESTINATION
AMARILLO,TX HOUSTON,TX
TYPE OF ACCIDENT
COLLISION WITH GROUND/WATER: CONTROLLED PHASE OF OPERATION TAKEOFF: INITIAL CLIMB

PROBABLE CAUSE(S)
PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT
FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - SIMULATED CONDITIONS

FIRE AFTER IMPACT

REMARKS- PIC, NON CFI, PULLED ENG AT VR.CO-PLT WITH NO LEAR DUAL INSTRUCTION MADE TKOF.ACFT VEERED, CRASHED.

Full narrative is not available