## NTSB Identification: LAX78FA040

14 CFR Part 135 Nonscheduled operation of NATNL JETS,INC Aircraft: LEAR 23, registration: N133W

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA	
3-2230	78/3/30 TIME - 22	BURBANK,CA 50			0	0	2	COMMERCIAL AIR TAXI-PASSG	AIRLINE TRANSPORT, AGE 25, 2600 TOTAL HOURS, 1680 IN TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - HOLLYWOOD-BURBANK									
	DEPARTURE	POINT	INTENDED DESTINATION							
	PHOENIX	, AZ	BURBANK,CA							
	TYPE OF ACCIDENT				PHASE OF OPERATION					
	COLLIDED WITH: FENCE, FENCEPOSTS			LANDING: ROLL						
	PROBABLE CAUSE(S)									
	AIRFRAME - LANDING GEAR: BRAKING SYSTEM (NORMAL SYSTEM)									
	MISCELLANEOUS ACTS,CONDITIONS - MATERIAL FAILURE									
	MISCELLANEOUS ACTS,CONDITIONS - HYDROPLANING ON WET RUNWAY									
	FACTOR(S) AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: WET RUNWAY WEATHER - RAIN									
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY RADIO									
	WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT									
	SKY CONDI	TION			C	EIL	ING	AT ACCIDENT SITE		
	OVERCAST			5000						
	VISIBILITY AT ACCIDENT SITE		ΓE		P	PRECIPITATION AT ACCIDENT SITE				
	4 MILES		RAIN SHOWERS							
	OBSTRUCTI NONE	ONS TO VISION AT	ACCIDENT SITE		F	RELATIVE BEARING OF WIND RIGHT QUARTERING HEAD WIND 023-067 DEGREES				
	TYPE OF W IFR	EATHER CONDITIONS	5		Т	YPE IF		FLIGHT PLAN		
	FIRE AFTER IMPACT									
	REMARKS- LEFT OUTBOARD ANTI-SKID VALVE INOP.PROPERTY DMG-ARPT FENCING.									

Full narrative is not available