

NTSB Identification: NYC78FA023

14 CFR Part 135 Nonscheduled operation of HENRY WEBER AI
 Aircraft: AEROSTAR 601P, registration: N1BE

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0033	78/1/24 TIME - 2005	DUBOIS, PA	AEROSTAR 601P N1BE DAMAGE-DESTROYED	CR- 1 0 0 PX- 1 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, AGE 26, 1230 TOTAL HOURS, 560 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - DUBOIS JEFFERSON						
DEPARTURE POINT		INTENDED DESTINATION				
DUBOIS, PA		LANCASTER, PA				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB		
COLLISION WITH GROUND/WATER: UNCONTROLLED				TAKEOFF: INITIAL CLIMB		
PROBABLE CAUSE(S)						
MISCELLANEOUS - FOREIGN MATERIAL AFFECTING NORMAL OPERATIONS						
MISCELLANEOUS ACTS,CONDITIONS - ICE-IN FUEL						
MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION						
MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES						
PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
FIRE AFTER IMPACT						
REMARKS- ICE WAS FOUND IN FUEL FLOW DIVIDER AND LINES.						

Full narrative is not available