

NTSB Identification: MIA78FKT22

14 CFR Part 91 General Aviation
Aircraft: CESSNA 401, registration: N80BW

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-4042	77/12/16	NR.W.PALM BEACH,FL	CESSNA 401	CR-	0	1	0	NONCOMMERCIAL
	TIME - 1523		N80BW	PX-	0	0	0	PLEASURE/PERSONAL TRANSP
			DAMAGE-DESTROYED	OT-	0	0	0	PRIVATE, AGE 54, 3454
								TOTAL HOURS, 16 IN TYPE,
								INSTRUMENT RATED.
		NAME OF AIRPORT - PALM BEACH INTL						
		DEPARTURE POINT INTENDED DESTINATION						
		WASHINGTON,DC POMPAHO BEACH,FL						
		TYPE OF ACCIDENT						
		ENGINE FAILURE OR MALFUNCTION						
		DITCHING						
		PROBABLE CAUSE(S)						
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
		PILOT IN COMMAND - LACK OF FAMILIARITY WITH AIRCRAFT						
		PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
		MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
		FACTOR(S)						
		MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER						
		PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE						
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER						

Full narrative is not available