

NTSB Identification: MIA78FA016

14 CFR Part 135 Scheduled operation of VIEQUES AIR LI
 Aircraft: BRITTNORMAN BN-2A, registration: N862JA

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4185	77/12/19	NR.VIEQUES,PR TIME - 0748	BRITTNORMAN BN-2A N862JA DAMAGE-DESTROYED	CR- 0 1 0 PX- 5 1 3 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-I	COMMERCIAL, FL.INSTR., AGE 50, 5031 TOTAL HOURS, 1010 IN TYPE, INSTRUMENT RATED.
		DEPARTURE POINT ST CROIX,VI	INTENDED DESTINATION VIEQUES,PR			
		TYPE OF ACCIDENT		PHASE OF OPERATION		
		ENGINE FAILURE OR MALFUNCTION		IN FLIGHT: NORMAL CRUISE		
		DITCHING		LANDING: LEVEL OFF/TOUCHDOWN		
		PROBABLE CAUSE(S)				
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING				
		PILOT IN COMMAND - MISMANAGEMENT OF FUEL				
		MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION				
		FACTOR(S)				
		MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES				
		MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER				
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES				
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER				

Full narrative is not available