

## NTSB Identification: SEA77FA047

14 CFR Part 91 General Aviation  
Aircraft: AEROSTAR 601P, registration: N9578Q

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3095	77/8/12 TIME - 1150	BURNS,OR	AEROSTAR 601P N9578Q DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	PRIVATE, AGE 38, 1008 TOTAL HOURS, 36 IN TYPE, NOT INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION		PHASE OF OPERATION		
LAVERN, CA		LAGRANDE, OR		IN FLIGHT: UNCONTROLLED DESCENT		
TYPE OF ACCIDENT		AIRFRAME FAILURE: IN FLIGHT			PROBABLE CAUSE(S)	
		PILOT IN COMMAND - EXCEEDED DESIGNED STRESS LIMITS OF AIRCRAFT				
FACTOR(S)		AIRFRAME - WINGS: SPARS				
		MISCELLANEOUS ACTS,CONDITIONS - OVERLOAD FAILURE				
		MISCELLANEOUS ACTS,CONDITIONS - SEPARATION IN FLIGHT				
		FIRE AFTER IMPACT				
REMARKS-		WINGS SEPARATED.				

Full narrative is not available