

NTSB Identification: LAX77FA065

14 CFR Part 135 Nonscheduled operation of AIR FAST FRGHT
 Aircraft: BEECH E18S, registration: N979SB

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3452	77/8/22 TIME - 2106	CATALINA IS,CA	BEECH E18S N979SB DAMAGE-DESTROYED	CR- 2 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-CARGO	COMMERCIAL, FL.INSTR., AGE 37, 2460 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - CATALINA DEPARTURE POINT CATALINA IS,CA INTENDED DESTINATION LONG BEACH,CA TYPE OF ACCIDENT COLLISION WITH GROUND/WATER: UNCONTROLLED PHASE OF OPERATION TAKEOFF: INITIAL CLIMB PROBABLE CAUSE(S) PILOT IN COMMAND - INCAPACITATION COPILOT - PHYSICAL IMPAIRMENT SYSTEMS - AIR CONDITION,HEATING AND PRESSURIZATION: OTHER MISCELLANEOUS ACTS,CONDITIONS - FATIGUE FRACTURE FACTOR(S) WEATHER - FOG WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED SKY CONDITION OBSCURATION CEILING AT ACCIDENT SITE UNKNOWN/NOT REPORTED VISIBILITY AT ACCIDENT SITE UNKNOWN/NOT REPORTED PRECIPITATION AT ACCIDENT SITE NONE OBSTRUCTIONS TO VISION AT ACCIDENT SITE FOG TYPE OF WEATHER CONDITIONS BELOW MINIMUMS TYPE OF FLIGHT PLAN NONE REMARKS- PILOT,CARBON MONOXIDE 45%,COPILOT 16.8%.CABIN HEATER,CRACKS IN COMBUSTION CHAMBER						

Full narrative is not available