## NTSB Identification: OAK78FVD54

14 CFR Part 91 General Aviation Aircraft: GRUMMAN TS-2A, registration: N448DF

FILE	DATE LOCATION	AIRCRAFT DATA	INJURIES F S M/N			FLIGHT PURPOSE	PILOT DATA	
3-2511	78/8/20 NR.LAYTONVILLE,CA TIME - 1746	GRUMMAN TS-2A N448DF DAMAGE-DESTROYED	CR- PX- OT-	0	0	0	COMMERCIAL FIRE CONTROL	AIRLINE TRANSPORT, AGE 29, 6273 TOTAL HOURS, 1912 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT UKIAH,CA TYPE OF ACCIDENT COLLIDED WITH: TREES PROBABLE CAUSE(S)	INTENDED DESTINATION LAYTONVILLE,CA		Р		F OPERATION LIGHT: LOW PASS		

PROBABLE CAUSE(S)
PILOT IN COMMAND - MISJUDGED DISTANCE, SPEED, AND ALTITUDE
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
FACTOR(S)
TERRAIN - HIGH OBSTRUCTIONS
FIRE AFTER IMPACT

Full narrative is not available