

NTSB Identification: OAK79FA013

14 CFR Part 135 Scheduled operation of UNION FLIGHTS
Aircraft: BEECH G18S, registration: N104KC

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT	PILOT DATA
				F	S	M/N	PURPOSE	
3-0058	79/1/4	SACRAMENTO,CA	BEECH G18S	CR-	2	0	0	ATP,FLIGHT INSTR., AGE
	TIME - 1738		N104KC	PX-	0	0	0	47, 17000 TOTAL HOURS,
			DAMAGE-DESTROYED	OT-	0	0	0	2000 IN TYPE, INSTRUMENT
								RATED.
	NAME OF AIRPORT - SACRAMENTO EXEC							
	DEPARTURE POINT		INTENDED DESTINATION					
	SACRAMENTO,CA		SAN FRANCISCO,CA					
	TYPE OF ACCIDENT			PHASE OF OPERATION				
	STALL			TAKEOFF: INITIAL CLIMB				
	PROBABLE CAUSE(S)							
	PILOT IN COMMAND - FAILED TO ABORT TAKEOFF							
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED							
	FIRE AFTER IMPACT							

Full narrative is not available