NTSB Identification: FTW78FA085

14 CFR Part 91 General Aviation Aircraft: AERO COMDR 500, registration: N6244B

FILE	DATE	LOCATION		F	S M	/N	PURPOSE		PILOT DATA	
3-2862			AERO COMDR 500							
	TIME - 2340		N6244B DAMAGE-DESTROYED	PX- 6	0	0 0	PLEASURE/PERSONA	L TRANSP	TOTAL HOURS, 142 IN TYPE NOT INSTRUMENT RATED.	
	DEPARTURE POINT									
	FT WORTH,TX		LAREDO,TX	SAN ANTONIO,TX						
	TYPE OF ACCIDENT			PHASE OF OPERATION						
	COLLISION WITH GROUND/WATER: UNCONTROLLED				IN FLIGHT: UNCONTROLLED DESCENT					
	PROBABLE CAUSE(S)									
	PILOT IN COMMAND - INITIATED FLIGHT IN ADVERSE WEATHER CONDITIONS									
	PILOT IN COMMAND - BECAME LOST/DISORIENTED									
	PILOT IN COMMAND - SPATIAL DISORIENTATION									
	FACTOR(S)									
	WEATHER - LOW CEILING									
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE									
	WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT									
	SKY CONDITION				CEILING AT ACCIDENT SITE					
	OVERCAST				2000					
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE					
	3 MILES OR LESS				UNKNOWN/NOT REPORTED					
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F					
	HAZE				73					
	WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS					
	50				7					
	TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN					
	IFR THE THE TWO IS TO SEE THE THE TWO IS TO SEE THE TWO IS THE TWO IS TO SEE THE TWO IS TO SEE THE TWO IS THE TWO I					NONE				
	FIRE AFTER IMPACT									
	REMARKS- DARK NIGHT,VFR FLT NOT RECOMMENDED.DURING LAST 11MIN OF FLT HEADING CHANGED THRU 630DEG.									

Full narrative is not available