

# NTSB Identification: CHI79FEC05

14 CFR Part 135 Nonscheduled  
Aircraft: BEECHCRAFT D-18S, registration: N80369

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4020	78/11/3	NR.FLINT,MI	BEECHCRAFT D-18S	CR- 0 0 1	COMMERCIAL	AIRLINE TRANSPORT, AGE
	TIME - 0427		N80369	PX- 0 0 0	AIR TAXI-CARGO	35, 2391 TOTAL HOURS, 247
			DAMAGE-DESTROYED	OT- 0 0 0		IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - BISHOP FLINT						
DEPARTURE POINT		INTENDED DESTINATION				
SAINT LOUIS,MO		FLINT,MI				
TYPE OF ACCIDENT				PHASE OF OPERATION		
COLLIDED WITH: PARKED AIRCRAFT				TAXI: FROM LANDING		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - FAILED TO SEE AND AVOID OTHER AIRCRAFT						
PILOT IN COMMAND - TAXIED/PARKED WITHOUT PROPER ASSISTANCE						
FACTOR(S)						
MISCELLANEOUS ACTS,CONDITIONS - WINDSHIELD,DIRTY,FOGGY,ETC.-RESTRICTED VISION						
REMARKS- PIPER PA-28-140,N54393,DESTROYED BY FIRE.						

Full narrative is not available