

# NTSB Identification: FTW79FQG45

14 CFR Part 91 General Aviation  
 Aircraft: MARTIN 404, registration: N40408

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2140	79/6/29 TIME - 0800	NR.MIAMI,TX	MARTIN 404 N40408 DAMAGE-DESTROYED	CR- 0 1 1 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AERIAL APPLICATION	ATP,FLIGHT INSTR., AGE 52, 15000 TOTAL HOURS, 61 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
PAMPA,TX		LOCAL				
TYPE OF ACCIDENT				PHASE OF OPERATION		
COLLIDED WITH: DIRT BANK				IN FLIGHT: SWATH RUN		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE						
MISCELLANEOUS ACTS,CONDITIONS - WINDSHIELD,DIRTY,FOGGY,ETC.-RESTRICTED VISION						
MISCELLANEOUS ACTS,CONDITIONS - SUNGLARE						
SPECIAL DATA						
TOTAL HOURS IN CROP CONTROL - 500		KIND OF OPERATION - OTHER				
KIND OF CROP - PASTURE		TYPE OF CHEMICAL USED - LIQUID CHEMICAL-NONTOXIC				
PILOT' S SEAT BELT -FASTENED-PROPERLY		GLOVES - USED				
GOGGLES - NOT USED		CRASH HELMET - AVAILABLE USED				
COCKPIT CRASHPAD - NOT INSTALLED		CRASH BAR - NOT INSTALLED				
TANK/HOPPER-LOCATION - BELLY		TERRAIN-TYPE -ROLLING				
ELEVATION-AREA BEING TREATED-FEET - 3000		SWATH RUN-HOW FLOWN - CROSSWIND				
FIRE AFTER IMPACT						
REMARKS- SPRAYING GRASSHOPPERS ON PASTURE LAND.PLT STATED SPRAY FROM ANOTHER ACFT COLLECTED ON WINDSHIELD.						

Full narrative is not available