NTSB Identification: LAX79FUJ80

14 CFR Part 91 General Aviation Aircraft: CESSNA 401B, registration: N77MG

FILE	DATE LOCATION		AIRCRAFT DATA	INJURIES F S M/N					PILOT DATA
3-1912	TIME - 1708	3	CESSNA 401B N77MG DAMAGE-DESTROYED	PX- 6	0	0	BUSINESS		PRIVATE, AGE 48, 519 TOTAL HOURS, 140 IN TYPE, NOT INSTRUMENT RATED.
	DEPARTURE POINT LONG BEACH CA		INTENDED DESTINATION PHOENIX,AZ						
	TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION COLLISION WITH GROUND/WATER: CONTROLLED				PHASE OF OPERATION IN FLIGHT: DESCENDING LANDING: LEVEL OFF/TOUCHDOWN				
	PROBABLE CAUSE(S) PILOT IN COMMAND - MISMANAGEMENT OF FUEL MISCELLANEOUS ACTS, CONDITIONS - FUEL STARVATION PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES								
	FACTOR(S) TERRAIN - WET,SOFT GROUND COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES								
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND FIRE AFTER IMPACT								
	REMARKS- PLT DIDN'T RECALL CHGNG FUEL SEL AFTER PWR LOSS-TIP TNKS SEP & BURNED.L AUX EMPTY.R AUX DEMOLISHED								

Full narrative is not available