

## NTSB Identification: FTW80FA019

14 CFR Part 91 General Aviation  
Aircraft: MITSUBISHI MU-2B, registration: N234MA

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3244	79/11/26	NR.POST OAK, TX	MITSUBISHI MU-2B TIME - 0555 N234MA DAMAGE-DESTROYED	CR- PX- OT-	1 0 0	0 0 0	NONCOMMERCIAL BUSINESS	AIRLINE TRANSPORT, AGE 39, 11274 TOTAL HOURS, 1045 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT JACKSON, MS			INTENDED DESTINATION ARDMORE, OK					
TYPE OF ACCIDENT COLLISION WITH GROUND/WATER: UNCONTROLLED						PHASE OF OPERATION IN FLIGHT: UNCONTROLLED DESCENT		
PROBABLE CAUSE(S) PILOT IN COMMAND - PHYSICAL IMPAIRMENT MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT								
FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - PILOT FATIGUE								
REMARKS- BLOOD ALCOHOL LVL-170MG PERCENT.NO SLEEP IN 48HRS.CRASHED ON AUTO-PLT HDG.HYPERACTIVE DOG ABD.								

Full narrative is not available