

NTSB Identification: NYC81FA087

14 CFR Part 91 General Aviation
Aircraft: AERO COMDR 680E, registration: N1520K

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-3281	80/9/16	NEW WINDSOR,NY	AERO COMDR 680E	CR-	1	0	0	NONCOMMERCIAL	PRIVATE, AGE 36, 182
	TIME - 1411		N1520K	PX-	1	0	0	PLEASURE/PERSONAL TRANSP	TOTAL HOURS, UNK/NR IN
			DAMAGE-DESTROYED	OT-	0	0	0		TYPE, NOT INSTRUMENT
									RATED.
		NAME OF AIRPORT - STEWART							
		DEPARTURE POINT		INTENDED DESTINATION					
		NEW WINDSOR,NY		HUDSON,NY					
		TYPE OF ACCIDENT			PHASE OF OPERATION				
		ENGINE FAILURE OR MALFUNCTION			TAKEOFF: INITIAL CLIMB				
		STALL			LANDING: TRAFFIC PATTERN-CIRCLING				
		PROBABLE CAUSE(S)							
		PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: IMPROPER MAINTENANCE (OWNER PERSONNEL)							
		PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED							
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE							
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND							
		FIRE AFTER IMPACT							
		REMARKS- CHAMPION RHB32E PLUGS INSTALLED,NOT APPROVED.COWL FASTENERS MISSING.							

Full narrative is not available